

~~SECRET~~**PRIORITY**

OUT55697

1965 MAY 10 22 05Z

P 102150Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
SECRET CITE NPIC 4496.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 101 WAS USED IN MISSION 8015 FLOWN ON 7 MAY 1965.

PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MANY SMALL EMULSION BLISTERS WITH ASSOCIATED LIFTS ARE PRESENT ON SEVERAL FRAMES INTERMITTENTLY THROUGHOUT THE MISSION. ALL POSITION INDICATOR LAMPS WERE INOPERATIVE THROUGHOUT. MINUS DENSITY DOTS SPACED 1.55" APART ARE LOCATED 1.3" FROM THE INBOARD EDGE IN THE FIRST 80 FRAMES. EVIDENCE OF MINOR PRESSURE ROLLER STATIC IS PRESENT ALONG THE OUTBOARD EDGE THROUGHOUT. MANY FINE LONGITUDINAL SCRATCHES ARE PRESENT IN THE EMULSION OF FRAMES 800 TO 899. THE FILM IS FOGGED ALONG THE OUTBOARD EDGE OF FRAME 2013. A MANUFACTURING SPLICE IS PRESENT IN THE FORMAT OF FRAME 191.

C. 9L SIDE: BOTH EDGES CONTAIN MINOR STATIC DISCHARGES. THE DATA CHAMBER TRACKS OFF THE EDGE OF THE FILM BUT NOT TO THE EXTENT THAT ANY INFORMATION IS LOST. (THE CUT-OFF LINE RUNS THROUGH

11 MAY 1965

COPIES RECEIVED 7			
CyNo.	Office	Act.	Recd
1	Master File		
2	OS		
	ADMIN		
	SEC BR		
	P&DS		
	CSD		
	HPD		
	FD		
3,4	PSD		
	TID		
	PSD		
	DA-10		
	DA-14		
	SEID		
	NSA LO		
	DIAAP		
	Destroyed		

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

THE CAMERA NUMBER BUT THE NUMBER IS READABLE). FRAME 386 CONTAINS A MANUFACTURER'S SPLICE AND HEAT SPLICES ARE POSITIONED BETWEEN FRAMES 915/916 AND 1500/1521.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000-2140.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUD COVER OBSCURES APPROXIMATELY 25 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

S E C R E T

/END OF MESSAGE/

THE CAMERA NUMBER BUT THE NUMBER IS READABLE). FRAME 386 CONTAINS A MANUFACTURER'S SPLICE AND HEAT SPLICES ARE POSITIONED BETWEEN FRAMES 915/916 AND 1500/1521.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000-2140.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUD COVER OBSCURES APPROXIMATELY 25 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

S E C R E T

/END OF MESSAGE/